

Corner I.D. # 102T

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 28, Township 8N, Range 2W,

Monument Description & Remarks: 2-1/2" Aluminum Monument, 30" long, set 0.1' below grade.
 (This monument is not a PLSS corner. It was set as part of a Geodetic Control Survey.)

Recovery Tie Drawing

West Isom Road


8/31/2016, Rachel Savich Oser, Fbk. 48, pg. 6
 7/24/2018, Cassidy Raley, Fbk. 52, pg. 22
 Monument recovered in fair condition
 Aluminum cap is not properly seated on rod, rod appears solid
 Eastern sky is partially obstructed by treeline

gravel drive

5.7' 59'

Wood Post w/
Steel cable

HARMONY CEMETERY



N
N.T.S.

Aluminum Monument
at Corner = ●

State Plane Coordinate (NAD83 Survey Feet, Indiana West Zone)-
 Northing: 1405396.55 Easting: 3080217.81 Elev.: 856.3

I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Matthew L. Cooper
 Indiana Registered Land Surveyor No. LS20200079
 COMPLETED By *Stu V. Tarkas*



ISON

7417 W
Ison RD7365 W
Ison RD

102T



0 50 100 200 Feet

Image Source: 2014 Monroe County Pictometry

Office of the Monroe County Surveyor
2004 Geodetic Control Project
119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570

